

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
	Impreza	FU(H4SO)	Throttle Body Inspection	FU 14, 15	Inspection notes were added and an inspection step was changed
2009		FU(H4DOTC)		FU 15	Inspection notes were added and an inspection step was changed
		SP(H4SO)	Accelerator Pedal Sensor	SP 5	A helpful note was added
		FU(H4SO)		FU 14, 15	Inspection notes were added and an inspection step was changed
2010	Impreza	FU(H4DOTC)	Throttle Body Inspection	FU 15 Inspection notes were added and inspection step was changed	Inspection notes were added and an inspection step was changed
		SP(H4SO)	Accelerator Pedal Sensor	SP 5	A helpful note was added
2011	Impreza	FU(H4SO)	Throttle Body Inspection	FU 14, 15	Inspection notes were added and an inspection step was changed
		SP(H4SO)	Accelerator Pedal Sensor	SP 5	A helpful note was added
2012		Drahas	Brake	Master Cylinder >Installation	Installation instructions and illustrations were changed
2012	Impreza	Brakes	DIdKe		Installation instructions and illustrations were changed
2013	Impreza/	Impreza/	Durlin	Master Cylinder >Installation	Installation instructions and illustrations were changed
	Crosstrek	Brakes	Brake	Brake Booster Installation instructions an >Installation illustrations were changed	

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2014	Impreza/ Crosstrek	Diagnostics	Hybrid Electric Vehicle Diag	Drive Cycle >Procedure >Drive Cycle J	Drive Cycle J was added
				Read Current Data > Operation >Hybrid Powertrain Control Systems	A row was added to the table
				Diagnostics w/ Phenomenon >Inspection >>Symptom Table >>Check Voltage Difference Between Blocks	A description and hyperlink were added to the symptom table and a TT was added
				Master Cylinder >Installation	Installation instructions and illustrations were changed
		Brakes	Brake	Brake Booster >Installation	Installation instructions and illustrations were changed
		Body & Electrical/ Wiring System	Security & Locks	Function Setting >Procedure >Method for Stopping KAS Function by Operating Access Key	A note about the secret code was added
				Drive Cycle >Procedure >Drive Cycle J	Drive Cycle J was added
2015	Impreza/ Crosstrek		Hybrid Electric Vehicle Diag	Read Current Data > Operation >Hybrid Powertrain Control Systems	A row was added to the table
				Diagnostics w/ Phenomenon >Inspection >>Symptom Table >>Check Voltage Difference Between Blocks	A description and hyperlink were added to the symptom table and a TT was added
		Brakes	Brake	Master Cylinder >Installation	Installation instructions and illustrations were changed
				Brake Booster >Installation	Installation instructions and illustrations were changed
2016	Impreza/ Crosstrek		Brake	Master Cylinder >Installation	Installation instructions and illustrations were changed
2010				Brake Booster >Installation	Installation instructions and illustrations were changed

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2017	Crosstrek	Body & Electrical/ Wiring System	Security & Locks	Function Setting >Procedure >Method for Stopping KAS Function by Operating Access Key	A note about the secret code was added
		Dustas	Brake	Master Cylinder >Installation	Installation instructions and illustrations were changed
		Brakes	DI dre	Brake Booster >Installation	Installation instructions and illustrations were changed
	Auto Headlight Beam Leveler Does Not Operate General Description >Component	Diagnostics	Headlight/ Foglight Diag		SRH Setup Status was added to the list
2017				Phenomenon >Inspection >The Auto Headlight	Changes were made to the TT
		Impreza		Description >Component >Master Cylinder	The master cylinder and brake pedal illustrations were changed
		Some instructions were changed and removed			
				>Installation >	
					A caution to not bend the brake pipe was changed
				>Installation	A caution about the clevis pin was changed

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
	Impreza/ Crosstrek	Body & Electrical/ Wiring System	Security & Locks	Function Setting >Procedure >Method for Stopping KAS Function by Operating Access Key	A note about the secret code was added
			Headlight/ Foglight Diag	Data Monitor >List	SRH Setup Status was added to the list
2018		Diagnostics		Diagnostics w/ Phenomenon >Inspection >The Auto Headlight Beam Leveler Does Not Operate	Changes were made to the TT
		Brakes	Brake	General Description > Component >Master Cylinder	The master cylinder illustration and tightening torque specs were changed
				Master Cylinder >Installation	Installation step #1 was changed for Crosstrek model
				Brake Booster >Installation > Brake Booster	Installation steps were changed
				Air Bleeding >Procedure >Caliper	Descriptions were deleted
				Brake Pipe >Installation	A caution to not bend the brake pipe was changed
			P-HEV Hybrid Powertrain Control Diag P-HEV Drive Motor Diag Plug-In Battery Charger Diag P-HEV High Voltage Battery	General Scan Tool >Operation >How to Use General Scan Tool > Mode \$07	Mode \$07 Description was Changed to Initial Emission-related Powertrain DTC
			Diag	Data Monitor	SRH Setup Status was added to the
2019	Impreza/ Crosstrek		Headlight/ Foglight Diag	>List Diagnostics w/	list
				Phenomenon >Inspection >The Auto Headlight Beam Leveler Does Not Operate	Changes were made to the TT
			P-HEV Drive Motor Diag	Diag Procedure w/ DTC >DTC P1CCC96	A change was made to step #2 of the TT

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2019	Impreza/ Crosstrek	Body & Electrical/ Wiring System	Security & Locks	Function Setting >Procedure >Method for Stopping KAS Function by Operating Access Key	A note about the secret code was added
(cont.)			Brake	Master Cylinder >Installation	Installation step #1 was changed for Crosstrek model
		Brakes		Brake Booster >Installation >Except for Hybrid Model	The installation instructions were changed
	Impreza/ Crosstrek		P-HEV Hybrid Powertrain Control Diag	General Scan Tool >Operation >How	Mode \$07 Description was Changed to Initial Emission-related Powertrain DTC
			P-HEV Drive Motor Diag	to Use General Scan Tool > Mode \$07	
			Plug-In Battery Charger Diag		
			P-HEV High Voltage Battery Diag	Data Monitor >List	
			Headlight/ Foglight Diag	Diagnostics w/ Phenomenon >Inspection >The Auto Headlight Beam Leveler Does Not Operate	SRH Setup Status was added to the list Changes were made to the TT
2020			P-HEV Drive Motor Diag	Diag Procedure w/ DTC >DTC P1CCC96	A change was made to step #2 of the TT
			Security & Locks	Function Setting >Procedure >Method for Stopping KAS Function by Operating Access Key	A note about the secret code was added
		Brakes	Brake	Master Cylinder >Installation	Installation step #1 was changed for Crosstrek model
				Brake Booster >Installation >Except for Hybrid Model	The installation instructions were changed

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2021		Diagnostics	Engine	Diag Procedure w/ DTC >P0011 >P0014 >P0021 >P0024	Steps were added to all four TTs
			P-HEV Drive Motor Diag	Diag Procedure w/ DTC >DTC P1CCC96	A change was made to step #2 of the TT Notes were added and inspection
	Impreza/ Crosstrek		Fuel Intertion	Throttle Body >Inspection >Throttle Sensor	Notes were added and inspection instructions were changed
		Engine	Fuel Injection	Engine Control Module >Installation	The immobilizer type was changed in the cautions section
			Speed Control Systems	Accelerator Pedal >Inspection >Except for Hybrid Model	A note was added