

ATTENTION:

GENERAL MANAGER ☐
 PARTS MANAGER ☐
 CLAIMS PERSONNEL ☐
 SERVICE MANAGER ☐

IMPORTANT - All
 Service Personnel
 Should Read and
 Initial in the boxes
 provided, right.

© 2021 Subaru of America, Inc. All rights reserved.



SUBARU

QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2008-22MY WRX
SUBJECT: Service Manual Corrections

NUMBER: 18-207-22
DATE: 08/22/22

INTRODUCTION

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2008	WRX	FU(STI)	FU(STI)	50	An Installation Caution Was Added
		BR	BR	13, 14, 18, 20	An Installation Caution Was Added
2009	WRX	FU(STI)	FU(STI)	57	An Installation Caution Was Added
		BR	BR	13, 14, 18, 20	An Installation Caution Was Added
2010	WRX	FU(STI)	FU(STI)	57	An Installation Caution Was Added
		BR	BR	13, 14, 18, 20	An Installation Caution Was Added
2011	WRX	FU(STI)	FU(STI)	57	An Installation Caution Was Added
		FU(w/o STI)	FU(w/o STI)	54	An Installation Caution Was Added
		BR	BR	19, 21, 30, 32	An Installation Caution Was Added
2012	WRX	Engine	Fuel Injection (STI & w/o STI)	Engine Control Module Installation	An Installation Caution Was Added
		Brakes	Brake	>Front Disc Rotor >Front Disc Brake Assembly >Rear Disc Rotor >Rear Disc Brake Assembly	An Installation Caution Was Added
2013	WRX	Engine	Fuel Injection (STI & w/o STI)	Engine Control Module Installation	An Installation Caution Was Added
2013	WRX	Brakes	Brake	>Front Disc Rotor >Front Disc Brake Assembly >Rear Disc Rotor >Rear Disc Brake Assembly	An Installation Caution Was Added

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Continued...

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2014	WRX	Engine	Fuel Injection (STI & w/o STI)	Engine Control Module Installation	An Installation Caution Was Added
2014	WRX & STI	Brakes	Brake	>Front Disc Rotor >Front Disc Brake Assembly >Rear Disc Rotor >Rear Disc Brake Assembly	An Installation Caution Was Added
2015	WRX & STI	Front Suspension	>General Description >Wheel Alignment	Specification >Front >Camber	Camber Tolerance Was Changed
		Engine	Mechanical	Engine Oil Pressure Inspection	Engine Oil Pressure Standard Was Changed
			Fuel Injection	Engine Control Module Installation	An Installation Caution Was Added
		Brakes	Brake	>Front Disc Rotor >Front Disc Brake Assembly >Rear Disc Rotor >Rear Disc Brake Assembly	An Installation Caution Was Added
				>Master Cylinder Removal >Brake Booster Removal >Brake Booster Inspection	Cautions Were Added and Air Tightness Check Notes Were Changed
			Parking Brake	Parking Brake Assembly Installation	An Installation Step Was Deleted And Another Step Was Changed
		Power Steering System	>General Description >Steering Gearbox	>Component >Disassembly & Assembly	The Illustration Was Changed and Items Were Added For The Guide Chip
		Suspension	Front Suspension	General Description >Front Suspension	The Illustrations Were Changed
			Rear Suspension	General Description >Rear Suspension	The Illustrations Were Changed
		Diagnostics	Engine Diagnostics	Diagnostic Procedure w/ DTC >P2270 >P2271	Step 3 of The Trouble Tree Was Changed
	WRX	Diagnostics	Cruise Control System	Diagnostic Procedure w/ Cancel Code	Connector & Terminal Numbers In CC 12 Trouble Tree Were Changed

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2016	WRX & STI	Front Suspension	>General Description >Wheel Alignment	Specification >Front >Camber	Camber Tolerance Was Changed
		Suspension	Front Suspension	General Description >Front Suspension	The Illustrations Were Changed
			Rear Suspension	General Description >Rear Suspension	The Illustrations Were Changed
		Engine Engine	Mechanical	Engine Oil Pressure Inspection	Engine Oil Pressure Standard Was Changed
			Fuel Injection	Engine Control Module Installation	An Installation Caution Was Added
		Brakes	Brake	>Front Disc Rotor >Front Disc Brake Assembly >Rear Disc Rotor >Rear Disc Brake Assembly	An Installation Caution Was Added
				>Master Cylinder Removal >Brake Booster Removal >Brake Booster Inspection	Cautions Were Added and Air Tightness Check Notes Were Changed
		Diagnostics	Engine Diagnostics	Diagnostic Procedure w/ DTC >P2270 >P2271	Step 3 of The Trouble Tree Was Changed
		Brakes	Parking Brake	Parking Brake Assembly Installation	An Installation Step Was Deleted And Another Step Was Changed
		Power Steering System	>General Description >Steering Gearbox	>Component >Disassembly & Assembly	The Illustration Was Changed and Items Were Added For The Guide Chip
	WRX	Diagnostics	Cruise Control System	Diagnostic Procedure w/ Cancel Code	Connector & Terminal Numbers In CC 12 Trouble Tree Were Changed
2017	WRX & STI	Suspension	Rear Suspension	General Description >Rear Suspension	The Illustrations Were Changed
		Engine	Mechanical	Engine Oil Pressure Inspection	Engine Oil Pressure Standard Was Changed
			Fuel Injection	Engine Control Module Installation	An Installation Caution Was Added
		Brakes	Brake	>Front Disc Rotor >Front Disc Brake Assembly >Rear Disc Rotor >Rear Disc Brake Assembly	An Installation Caution Was Added
				>Master Cylinder Removal >Brake Booster Removal >Brake Booster Inspection	Cautions Were Added and Air Tightness Check Notes Were Changed
			Parking Brake	Parking Brake Assembly Installation	An Installation Step Was Deleted And Another Step Was Changed
		Power Steering System	>General Description >Steering Gearbox	>Component >Disassembly & Assembly	The Illustration Was Changed and Items Were Added For The Guide Chip
		Diagnostics	Engine Diagnostics	Diagnostic Procedure w/ DTC >P2270 >P2271	Step 3 of The Trouble Tree Was Changed
		Suspension	Front Suspension	General Description >Front Suspension	The Illustrations Were Changed
			Rear Suspension	General Description >Rear Suspension	The Illustrations Were Changed

Continued...

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2017 cont.	WRX	Diagnostics	Cruise Control System	Diagnostic Procedure w/ Cancel Code	Connector & Terminal Numbers In CC 12 Trouble Tree Were Changed
			Reverse Assist Braking Diagnostics	Diagnostic Procedure w/ DTC >B2C11	Step 2 Of The Trouble Tree Was Changed
2018	WRX & STI	Suspension	Front Suspension	General Description >Specification	Camber Tolerance Was Changed
			Front Suspension	General Description >Front Suspension	The Illustrations Were Changed
			Rear Suspension	General Description >Rear Suspension	The Illustrations Were Changed
		Diagnostics	Eyesight Diag	Diagnostic Procedure w/ ECU Cancel Code > 12	Trouble Tree Connector & Terminal Were Changed
		Engine	Fuel Injection	Engine Control Module Installation	An Installation Caution Was Added
		Brakes	Brake	>Master Cylinder Removal >Brake Booster Removal >Brake Booster Inspection	Cautions Were Added and Air Tightness Check Notes Were Changed
		Power Steering System	>General Description >Steering Gearbox	>Component >Disassembly & Assembly	The Illustration Was Changed and Items Were Added For The Guide Chip
		Engine	Mechanical	Engine Oil Pressure > Inspection	Engine Oil Pressure Standard Was Changed
	STI	Diagnostics	Engine Diagnostics	Diagnostic Procedure w/ DTC > P2270	Connector & Terminal For Trouble Tree Step 3 Were Changed
	WRX	Diagnostics	Cruise Control System	Diagnostic Procedure w/ Cancel Code	Connector & Terminal Numbers In CC 12 Trouble Tree Were Changed
			Reverse Assist Braking Diagnostics	Diagnostic Procedure w/ DTC >B2C11	Step 2 Of The Trouble Tree Was Changed
			Engine Diagnostics	Diagnostic Procedure w/ DTC > P2270 > P2271	Chnages Were Made to Step 3 On Both Trouble Trees
2019	WRX & STI	Engine	Mechanical	Engine Oil Pressure > Inspection	Engine Oil Pressure Standard Was Changed
		Suspension	Front Suspension	General Description >Specification	Camber Tolerance Was Changed
				General Description >Front Suspension	The Illustrations Were Changed
			Rear Suspension	General Description >Rear Suspension	The Illustrations Were Changed
		Engine	Fuel Injection	Engine Control Module Installation	An Installation Caution Was Added
		Brakes	Brake	>Master Cylinder Removal >Brake Booster Removal >Brake Booster Inspection	Cautions Were Added and Air Tightness Check Notes Were Changed
		Power Steering System	>General Description >Steering Gearbox	>Component >Disassembly & Assembly	The Illustration Was Changed and Items Were Added For The Guide Chip
	STI	Diagnostics	Engine Diagnostics	Diagnostic Procedure w/ DTC > P2270	Connector & Terminal For Trouble Tree Step 3 Were Changed

Continued...

YEAR	MODEL	SECTION	SUB-SECTION	PAGE or CHAPTER	DESCRIPTION OF CHANGE
2019 cont.	WRX	Diagnostics	Cruise Control System	Diagnostic Procedure w/ Cancel Code > 12	Connector & Terminal Numbers In CC 12 Trouble Tree Were Changed
			Eyesight Diag	Diagnostic Procedure w/ ECU Cancel Code > 12	Trouble Tree Connector & Terminal Were Changed
			Reverse Assist Braking Diagnostics	Diagnostic Procedure w/ DTC >B2C11	Step Two of The Trouble Tree Was Changed
			Engine Diagnostics	Diagnostic Procedure w/ DTC > P2270 > P2271	Chnages Were Made to Step 3 On Both Trouble Trees
2020	WRX & STI	Engine	Mechanical	Engine Oil Pressure > Inspection	Engine Oil Pressure Standard Was Changed
		Suspension	Front Suspension	General Description >Specification	Camber Tolerance Was Changed
				General Description >Front Suspension	The Illustrations Were Changed
		Brakes	Brake	Front Disc Rotor & Front Disc Brake Assembly >Installation	A Caution Was Added
				Rear Disc Rotor & Rear Disc Brake Assembly > Installation	A Caution Was Added
				>Master Cylinder Removal >Brake Booster Removal >Brake Booster Inspection	Cautions Were Added and Air Tightness Check Notes Were Changed
		Power Steering System	>General Description >Steering Gearbox	>Component >Disassembly & Assembly	The Illustration Was Changed and Items Were Added For The Guide Chip
	STI	Diagnostics	Engine Diagnostics	Diagnostic Procedure w/ DTC > P2270	Connector & Terminal For Trouble Tree Step 3 Were Changed
	WRX	Diagnostics	Engine Diagnostics	Diagnostic Procedure w/ DTC > P2270 > P2271	Chnages Were Made to Step 3 On Both Trouble Trees
			Cruise Control System	Diagnostic Procedure w/ Cancel Code > 12	Connector & Terminal Numbers In CC 12 Trouble Tree Were Changed
			Eyesight Diag	Diagnostic Procedure w/ ECU Cancel Code > 12	Trouble Tree Connector & Terminal Were Changed
			Reverse Assist Braking Diagnostics	Diagnostic Procedure w/ DTC >B2C11	Step Two of The Trouble Tree Was Changed
2022	WRX	Diagnostics	Transmission Diagnostics	Diag w/ Phenomenon >List >Inspection	List & Symptom Table Were Added and Inspection #1 Was Changed