

GPOP - Issue Review System

Part Number: 05154400A\$

Part Description: Pump - Power Steering Hydraulic

Issue Description: NOTE: This Tech Tip is for gasoline engine JK vehicles only, manufactured before August 26, 2015.

If the power steering pump is being replaced because the power steering fluid flow or pressure readings are below specification, the power steering fluid reservoir and cap assembly should also be replaced.

Power steering reservoir and cap assembly 52126151AG or later should be used.

~ ~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
