

Toyota Motor Sales, U.S.A., Inc. 19001 South Western Avenue Torrance, CA 90501 (310) 468-4000

Posted 07/21/2016

## Safety Recall and Service Campaign - Technician Certification Requirements

**IMPORTANT:** 

Refer to the following matrix to determine the technician certification requirements for each specific Safety Recall or Service Campaign. Special Courses and Additional Requirements are noted in the two columns on the far right.

Refer to the Dealer Letter of the specific Safety Recall or Service Campaign for more information.

Safety Recall or Service	r of the specific Safety Recall or Service Campaign for more inforn  Description	nation.	<u> </u>	Ceri	Ce tified	ertifica	tion Lev		uiremer Expert			<u> </u>		Special	Additional Requirements
ISCIGOT	Certain 2016 Model Year Prius	Maint	EG	DT ✓	CH ✓	EL ✓	EG	DT ✓	CH ✓	EL ✓	HY ✓	Mast √	MDT ✓	Courses SC15A	Additional Requirements
Safety Recall G0M	Simple Advance Parking Guidance System 2015-2016 Model Year Toyota Prius V Emission Control Information Label		<b>√</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>√</b>	✓	✓	✓	<b>✓</b>	✓	✓	SC15A	
LSC GOL	2016 Model Year Scion iA Inspection and Adjustment of Coolant Concentration 2016 Model Year Scion iA		<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	SC15A	
LSC GOK Safety Recall GOI	Spare Tire Pressure Adjustment Certain 2016 Model Year Avalon, Avalon HV & Camry		<b>✓</b>	<b>✓</b>	<b>√</b>	<b>✓</b>	✓ ✓	✓ ✓	✓ ✓	✓ ✓	✓ ✓	<b>✓</b>	✓ ✓	SC15A SC15A	
Safety Recall GOI	Occupant Classification System (OCS)  Certain 2016 Model Year RAV4  Brake Actuator Inspection/Replacement				✓				<b>√</b>			✓	✓	SC15A	
Safety Recall G0H	Certain 2016 Model Year Sienna Front Driver and Passenger Seat Belt Height Adjuster Replacement 2015-2016 Model Year Toyota Sienna		✓	✓	✓	✓	✓	<b>√</b>	<b>√</b>	✓	✓	✓	✓	SC15A	
Safety Recall GOG Safety Recall GOF	Oxygen Sensor Replacement 2006-2012 Rav4, 2012-2014 Rav4 EV		✓ ✓	✓ ✓	✓	✓	✓	✓ ✓	✓ ✓	✓ ✓	✓	✓ ✓	✓ ✓	SC15A SC15A	
	Rear Outboard Seatbelts  Certain Model 2013 - 2016 Model Year Scion FR-S  Ignition Key Interlock System (Automatic Transmission Models with Ignition Key		<b>√</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>✓</b>	<b>√</b>	<b>√</b>	SC15A	
Safety Recall FOV	ONLY) Certain 2013-2015 Model Year Avalon, Avalon HV Pre-Collision System						✓	<b>√</b>	<b>√</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	SC15A SCF0V	
SSC FOLL	, and the second		<b>√</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>/</b>		*If inspection determines the vehicle requires additional electrical repairs, it must be preformed
	Certain 2010 - 2014 Model Year Tacoma 2TR-FE Vehicles Exhaust Pipe Replacement for Catalytic Converter 2016 Tacoma							,				Ĺ			by a technician who is expert or above
Safety Recall FOR	Driver Knee Airbag Module Bolts 2012-2014 Model Year Prius V		<b>√</b>	<b>√</b>	<b>√</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	✓ ✓	✓ ✓	✓ ✓	SC15A SC15A	
Safety Recall FOP	Software Update for Motor Generator ECU and Power Management ECU  2007 Model Year Highlander Hybrid  Engineer Software Update for Air Fuel (A/F) Sensor Monitoring		<b>√</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>√</b>	✓	✓	✓	<b>√</b>	✓	✓	SC15A	
LSC FON	2014 Model Year Corolla Eco (2ZR-FAE) ECM Software Update for Variable Valve Lift Control 2011 Model Year Sienna		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	SC15A	
LSC FOM Safety Recall FOI	3rd Row Seat Back Panel Replacement 2004-2005 Model Year RAV4		<b>√</b>	<b>✓</b>	<b>√</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>√</b>	✓ ✓	<b>✓</b>	✓ ✓	✓ ✓	SC15A SC15A	
Safety Recall FOK	Front Driver Airbag Inflator Module  2015 Model Year Scion tC Vehicles Rear Suspension Arm				✓				<b>√</b>			<b>√</b>	<b>√</b>	SC15A	
Safety Recall FOI	2014-2015 Model Year RAV4, 2015 Highlander and Highlander HV, and 2015 Camry and Camry HV Vehicles				<b>✓</b>				<b>√</b>			✓	✓	SC15A	
Safety Recall FOI	2012 - 2014 Model Year RAV4 Electric (EV) EV Traction Motor Assembly										<b>√</b>	<b>√</b>	<b>√</b>	SC15A	012D
	2012 - 2015 Model Year Yaris Hatchback		<b> </b>	<b> </b>	<b>✓</b>	<b> </b>	<b> </b>	<b>√</b>	<b>√</b>	<b>√</b>	<b> </b>	<b>√</b>	_	SC15A	
,	Headliner Replacement  TRD Accessory Wheels and Light Truck Tires  Tire and							ĺ				· 			
Safety Recall FUG	Loading Information Label  2015 Model Year Yaris			<b>√</b>	✓ ✓	<b>✓</b>	<b>√</b>	<b>√</b>	✓ ✓	<b>√</b>	<b>√</b>	<b>1</b>		SC15A	
Safety Recall FOF	Rear Axle Hub Bearing Torque Confirmation  Certain 2014 Model Year FJ Cruiser Vehicles  Steering Intermediate Shaft Assembly				✓ ✓		-		✓ ✓			<b>✓</b>	<b>✓</b>	SC15A SC15A	
Safety Recall FOD	Certain 2011-2012 Model Year Avalon Vehicles Premium Audio System - Rear Sub-Woofer					<b>✓</b>				✓		<b>✓</b>	✓	SC15A	
FOC	Certain 2014 and Early 2015 Model Year Prius V Vehicles Occupant Classification System (OCS) Sensor Certain 2012-2013 Model Year Prius C and Yaris Hatchback Vehicles						✓	<b>✓</b>	<b>√</b>	√	✓	✓	✓	SC15A	
LSC FOB	Occupant Classification System (OCS) Sensor Certain 2012-2014 Model Year Tundra and Sequoia Vehicles		<b>√</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>	✓ ✓	<b>✓</b>	✓ ✓	✓ ✓	SC15A SC15A	
Safety Recall F07	ECM Software Update Certain 2015 Model Year Sienna Vehicles Second Row Overhead Assist Grips						✓	<b>√</b>	<b>√</b>	✓	<b>√</b>	✓	✓	SC15A	
Safety Recall E05	Certain 2014 Model Year Avalon, Avalon Hybrid, Camry, and Camry Hybrid Vehicles Driver Side Front Suspension Lower Arm				<b>✓</b>				<b>✓</b>			<b>✓</b>	<b>√</b>	SC15A	
Safety Recall E04 – High	Certain 2003 – 2005 Model Year Corolla, Corolla Matrix, and Tundra Vehicles Front Passenger Airbag Inflator Module									✓		✓	<b>√</b>	SC15A, SC13B	
ISC FO3	Certain 2012-2014 Model Year Camry Vehicles U760 ATM ECM Software Update		<b>√</b>	<b>✓</b>	✓	<b>√</b>	<b>√</b>	<b>✓</b>	<b>✓</b>	✓	<b>✓</b>	✓	<b>√</b>	SC15A	
Safety Recall F02	Rear Leaf Spring Replacement Certain 2005 - 2011 Model Year Tacoma				✓				<b>√</b>			<b>√</b>	<b>√</b>	SC15A	Remedy launched for vehicles in Boston, New York CAT, Cincinnati, Denver, Portland and Chicago
Safety Recall F01	Certain 2014 MY Avalon, Camry, Highlander and Sienna Vehicles Equipped with		<b>√</b>	<b>✓</b>	✓	<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>✓</b>	SC15A	regions.
Safety Recall F07	2GR-FE Engine – Potential Fuel Delivery Pipe Leak Certain 2014 Model Year Tundra Double Cab and CrewMax Vehicles Curtain Shield Airbag						<b>✓</b>	✓	<b>√</b>	✓	<b>✓</b>	✓	✓	SC15A	
EOY	Certain 2014 MY FJ Cruiser Trail Teams Ultimate Edition Package Lower Ball Joint Bolt Certain 2008-2014 MY Tacoma and FJ Cruiser				✓				✓			✓	✓	SC15A	
E0X Safety (Noncompliance) Recall	TRD Accessory Wheels and Toyota Recommended LT Tires Certain 2014 Model Year Sienna Vehicles		✓ ✓	✓ ✓	✓ ✓	✓ ✓	✓	✓	✓ ✓	✓ ✓	✓ ✓	✓ ✓	✓ ✓	SC15A SC15A	
LSC FOLL	Transmission Shift Control Cable 2007-2011 Model Year Camry Hybrid Vehicles Brake Reservoir Tank Replacement							ŕ	√ ·	<u> </u>		√	√	SC15A	
Safety Recall EOT	Certain 2014 Model Year Highlander and Highlander HV Passenger Seatbelt Selectable Force Limiter – Software Update						✓	<b>√</b>	<b>√</b>	✓	✓	✓	✓	SC15A	
Special Service Campaign ESS	Certain 2004-2011 Model Year Sienna 2WD Vehicles Equipped w/ a Spare Tire - Excessive Corrosion of the Spare Tire Carrier Cable Certain 2004-2011 Model Year Sienna 2WD Vehicles Equipped w/ a Spare Tire -		√ √	√	1	√ √	√ √	1	1	√ √	√	<b>√</b>	√ √	SC15A SC15A	
Safety Recall FOR	Excessive Corrosion of the Spare Tire Carrier Cable 2014 Model Year Highlander Vehicles 2nd Row Passenger-Side Inboard Seat Track for 60/40 Split Seat		<b>√</b>	<b>√</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>√</b>	<b>✓</b>	<b>✓</b>	SC15A	
LSC EOP	Certain 2014 Model Year Toyota Highlander Hybrid Vehicles Coolant Hose Clearance										<b>√</b>	✓	✓	SC15A	
LSC EUN	Certain 2011-2014 Model Year Toyota Sienna Pre-Collision System (PCS) Driving Support ECU 09-10 Corolla, 09-10 Matrix, 08-10 Highlander, 09-10 Tacoma, 06-10 Rav4, 06-10			_		<b>√</b>				<b>√</b>		<b>√</b>	<b>√</b>	SC15A	
Safety Recall FOI	Yaris; Spiral Cable 06-10 Yaris HB, 07-10 Yaris Sedan, and 08-10 Scion xD; Driver's Seat Track		<b>√</b>	<b>✓</b>	<b>✓</b>	✓ ✓	<b>√</b>	<b>✓</b>	<b>✓</b>	✓ ✓	<b>✓</b>	<b>✓</b>	✓ ✓	SC15A SC15A	
LSC EOK	Assembly & Passenger Track Assembly (3-Door Yaris Only) 2014 MY Avalon, Avalon Hybrid, Highlander, and Sienna Vehicles Safety Connect System Disabled		<b>√</b>	<b>√</b>	<b>✓</b>	<b>√</b>	<b>√</b>	✓	✓	✓	<b>√</b>	✓	<b>√</b>	SC15A	
LSC EOJ	Certain 2013-2014 Model Year Avalon & Avalon HV Driver & Passenger Front Seatback Board 2013 Highlander		✓	<b>√</b>	✓	✓	✓	<b>√</b>	✓	✓	✓	✓	✓	SC15A	
Recall EOH	2nd Row Left Hand Seat Inboard Seat Track 2003-2004 Avalon		<b>√</b>	<b>✓</b>	<b>√</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>√</b>	✓ ✓	<b>✓</b>	✓ ✓	✓ ✓	SC15A SC15A	
Safety Recall FOF	Supplemental Restraint System (SRS) Electronic Control Module 2012-2013 Tacoma, 2012 RAV4 Brake Actuator Reprogramming						<b>√</b>	<b>✓</b>	<b>✓</b>	✓	<b>✓</b>	<b>√</b>	<b>√</b>	SC15A	
Safety Recall E0E	2010-2014 Prius Software Update for Motor Generator ECU & Power Management ECU Safety (Non-Compliance) Recall EOC									_	<b>✓</b>	✓	<b>✓</b>	SC15A	
Recall EOC Safety (Non-Compliance)	2014 Highlander; 3rd Row Center Seat Belt Multiple 2013-2014 Models		<b>✓</b>	<b>✓</b>	✓	✓	<b>√</b>	✓	✓	✓ ✓	<b>✓</b>	✓	✓ ✓	SC15A SC15A	
Safety Recall DSF	Seat Heater Assemblies 03-04 MY Corolla, Matrix, & Tundra and 02-Early 04 MY Sequoia Front Passenger Airbag Inflator Module									✓		<b>✓</b>	<b>✓</b>	SC15A, SC15A, SC13B	
Safety Recall DSB	2003-2004 Corolla and Corolla Matrix Supplemental Restraint System (SRS) Electronic Control Module (ECM)									✓		✓	✓	SC15A	* Your Regional Office may have specific requirements to perform this remedy. Please
Safety Recall DOU	2013-2014 Tacoma 4 Cylinder Valve Spring Replacement						<b>√</b>	✓				<b>√</b>	<b>√</b>	SC15A	confirm with them prior to starting
Safety Recall DUT	2012-2013 Avalon, Camry, Camry HV, and Venza, 2013 Avalon HV HVAC Assembly 2013 Avalon & Avalon HV, 2013-2014 Camry & Camry HV, 2014 Corolla									✓		✓	<b>✓</b>	SC15A	
Safety Recall DOS	Windshield Wiper Switch 2004-2005 and 2007-2009 Sienna		<b>√</b>	<b>✓</b>	<b>/</b>	✓ ✓	<b>✓</b>	<b>✓</b>	<b>√</b>	✓	<b>✓</b>	✓ ✓	✓ ✓	SC15A SC15A	
LSC DON	Shift Lock Solenoid Assembly 2011-2012 Highlander HV Rear Driveshaft Assembly Replacement							<b>√</b> **			<b>✓</b>	<b>✓</b>	<b>✓</b>	071, SC15A	**Drivetrain Expert and completion of course 071 Toyota Hybrid System
Safety Recall D0M	2006-2010 Highlander HV Intelligent Power Module (IPM) Replacement 2005-2011 Tacoma Access Cab Vehicles										<b>✓</b>	<b>√</b>	✓	SC15A	
Safety Recall DOL	Driver and Front Passenger Seat Belt Assemblies 2012 Yaris			_	_	✓ ✓				✓		✓ ✓	✓ ✓	SC15A SC15A	
·	Power Steering Control Module  Safety Recall DOH: 2010 Prius; Brake Booster Pump Assembly (Accumulator)		_		<b>✓</b>	-	_		<b>√</b>	•		· ·	· ·	SC15A SC15A	
, , , , , ,	2007-2013 FJ Cruiser Genuine Toyota Auxiliary Light Kit Accessory														* Your Regional Office may have specific requirements to perform this remedy. Please
Safety Recall DOF	2003-2004 Corolla, Matrix, Tundra and 2002-2004 Sequoia Front Passenger Airbag Inflator Module									✓		<b>√</b>	✓	SC15A, SC13B	confirm with them prior to starting
	2007 - 2013 FJ Cruiser Access Door Inner Panel		<b>√</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>✓</b>	✓	✓	<b>✓</b>	<b>√</b>	<b>✓</b>		* Your Regional Office may have specific requirements to perform this remedy. Please
Satety Recall DOC	2003-2004 Corolla and Corolla Matrix									✓		<b>√</b>	<b>✓</b>	SC15A	confirm with them prior to starting  * Your Regional Office may have specific requirements to perform this remedy. Please
Safety Recall DOC	Supplemental Restraint System (SRS) Flectronic Control Module (ECM)	1	<u> </u>	<del>                                     </del>	<del>                                     </del>	_			<b>✓</b>			<b>✓</b>	<b>✓</b>	SC15A, SC13C	confirm with them prior to starting
Safety Recall DOC  Safety Recall DOB  Safety Recall CSI	Supplemental Restraint System (SRS) Electronic Control Module (ECM)  2006-2011 RAV4  Rear Lower Suspension Arm No.1					I					_	_	•	ししょうし	
Safety Recall DOC  Safety Recall DOB  Safety Recall CSJ						_				÷	-		•		
Safety Recall DOC  Safety Recall DOB  Safety Recall CSJ  Safety Recall COM	2006-2011 RAV4 Rear Lower Suspension Arm No.1 Certain 2007-2008 Yaris, 2007-2009 Rav4, 2007-2009 Tundra, 2007-2009 Camry,		<b>✓</b>	<b>√</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	<b>√</b>	<b>√</b>	✓	SCC0M2	
Safety Recall DOC  Safety Recall DOB  Safety Recall CSJ  Safety Recall COM	2006-2011 RAV4 Rear Lower Suspension Arm No.1  Certain 2007-2008 Yaris, 2007-2009 Rav4, 2007-2009 Tundra, 2007-2009 Camry, 2007-2009 Camry HV, 2008-2009 Scion xD, 2008-2009 xB, 2008-2009 Sequoia, 2008 Highlander and Highlander HV, 2009 Corolla, and 2009 Matrix Vehicles		✓	<b>✓</b>	<b>✓</b>	<b>✓</b>	✓	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>✓</b>	<b>√</b>	✓		
Safety Recall DOC  Safety Recall DOB  Safety Recall CSJ  Safety Recall COM  LSC 90K  Warranty Ehancement Program ZF5	2006-2011 RAV4 Rear Lower Suspension Arm No.1  Certain 2007-2008 Yaris, 2007-2009 Rav4, 2007-2009 Tundra, 2007-2009 Camry, 2007-2009 Camry HV, 2008-2009 Scion xD, 2008-2009 xB, 2008-2009 Sequoia, 2008 Highlander and Highlander HV, 2009 Corolla, and 2009 Matrix Vehicles Power Window Master Switch (PWMS)  Multiple Models and Model Years		✓	✓ ————————————————————————————————————	<b>✓</b>	<b>✓</b>	✓	<b>*</b>	✓ ·	<b>√</b>	<b>✓</b>	✓ ✓	✓	SCC0M2	