

## Recall Reminder

October, 2012

## Please contact your Ford dealer today regarding Recall 12S35.

There is no charge to vehicle owners for recall repairs performed by an authorized dealer. If your dealer has recently completed this recall repair, please disregard this reminder.

Thank you for your attention to this very important matter.

Year/Model: 2013 Escape

VIN#:

Subject: Fuel Jumper Line Replacement

**Ford Customer Service Division**