

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS4975
URGENT - DISTRIBUTE IMMEDIATELY

Date: February 12, 2019

Subject: N182206630 - Safety Recall
Airbag Inflator Rupture
Partial Release

Models: 2010-2011 Chevrolet Malibu

To: All General Motors Dealers

General Motors is releasing Safety Recall N182206630 today. The total number of U.S. vehicles involved is approximately 1,145. Please see the attached bulletin for details.

Dealers were notified of this safety recall on December 21, 2018. Sufficient stock of replacement parts to begin servicing vehicles with cocoa or titanium-color interiors are now available. GM expects replacement parts for vehicles with other interior colors to be available in mid-to-late March.

This bulletin contains the remedy instructions for the vehicles with cocoa and titanium-colored airbag modules. Dealers will be advised when replacement parts are available to repair the remaining vehicles. Until that time, the IVH screen in GWM will display "N/A" under Release Date and "Incomplete – Remedy not yet available" under Status. This means the required repair is not yet available and dealers should not attempt to perform the repair on that vehicle. Once the service procedure contained in the bulletin has been performed on the vehicle, the vehicle is released from stop delivery and the vehicle can be delivered to the customer.

NOTE: If component parts are not available to repair a customer's vehicle involved in this recall and the customer requests alternate transportation, the dealer may provide a rental vehicle to the customer free of charge until component parts are available to repair the customer's vehicle. Standard courtesy transportation is also available while a customer's vehicle is being serviced. This bulletin also includes information for courtesy transportation submission in the warranty information section.

Customer Letter Mailing

The customer notification letter mailing began on February 8, 2019.

Global Warranty Management (GWM)

The Investigate Vehicle History (IVH) screen in the GWM system will be updated February 12, 2019. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS